







sales@primepac.co.nz

GENERAL PRODUCT INFORMATION

Product Name: Pneumatic Inflation Tool

Product Code: 5215

Date of Issue: 18/06/2021



Description:

Fast and *simple*, that are the two words to describe this new inflation tool. And it is easy and save to operate.


- Press the handle to open the fork and apply it to the MegaFlow valve.
- Release the handle when the inflator is on the valve to open it. You can hold the whole bag easy up with this inflator.
- Open the hand slide valve (blue) on the inflators end to start inflating. The bag will inflate very fast.
- When the bag start building up pressure, the over flow air stream will come out of the top opening of the inflator.
- To built up more pressure in the bag, simply close the top opening with your hand for some seconds.
- When the bag have reached your desired filling presure, press the inflator handle again and the MegaFlow valve will close automatically.
- Finally remove the inflator from the valve and close the blue hand slide valve.

Product Specifications

Design:	Nylon body, fast filling inflation tool for MV valves

Size: 1 inch









Rosedale, Auckland

www.primepac.co.nz

Weight: 0.36 kg

Material: Nylon Plastic

Product Name	Pneumatic Inflatio	Inspection	n Date	2021.6.16			
Product description	Mega Flow Air	Inspector		DongMin			
General guidelines	Refer to MIL-STD 105E, normal sampling and level-II for sampling check the submitted batch						
	QC do the inspection according to QC SIP, Engineering spec., customer requirements, QC sample						
Actual inspection Result	Major defect Q'ty	0	Final Bassas		Reviewed by	DongMin	
	Minor defect Q'ty	0	Judgement	Passed	Approved by	<u>Belle</u>	





Product	photo			Air inflation test			
		_	 				

Dimention measure	Specification: L 295 x W 50 x H 90_ mm ; Weight: 0.29kg							
	1# 2# 3#					Judgement		
Length (cm)	294.5	295	295.5			OK		
Width(cm)	49.5	50	50.5			OK		
Height(cm)	89.5	90	90.5			OK		
Weight(kg)	0.28	0.29	0.30			OK		
	Inspect and Measurement Record							
Check Items		General checklist				Major Q'ty	Minor Q'ty	
Appearance Inspection	No sharp po	oint or edge	0	0				
	No rusting,	coating pee	0	0				
	No serious	surface scra	0	0				
	No deforme	d, cracked	0	0				

Appearance Inspection	No rusting, coating peel off	0	0
	No serious surface scrachted	0	0
	No deformed, cracked for component parts	0	0
	Oil mark, dirty mark	0	0
Function Test	Slipping check: the belt does not slip from the clamp during hand tesnsion test	0	0
	Mechanical check:the unit works well under the max. loding of the tensioned belt, all the parts functional ok, no damaged	0	0
Printing or labelling	No serious color difference	0	0
	Contents correct, clear and readable	0	0
	Shipping mark and carton label correct	0	0
Packaging	Right product and quantity packed with defined packing way	0	0
	No borken and deformation with the carton and pallet	0	0
Remarks	Full inflation of dunage air bag with inflator.		